

PWD

Office of the Executive Engineer
PWD No.1, 8th Floor, Thane Mahanagar Palikha
Parking Plaza Building, Near Jupiter Hospital,
Thane (W), 400 601

Govt. of
Maharashtra

PH:022 25369293

Web Site: www.pwd.maharashtra.gov.in

Email: thane1.ee@mahapwd.gov.in

O.W.No.V/PWD/Thane-1/Plan Branch/9610

Date: 9/10/2026

To,
Mar Thoma Vidyapeeth, Goveli,
At Goveli, Post Rayta, Taluka Kalyan,
Thane.

Sub: Regarding issuing of Certificate of the building is safe.

- Ref: 1) Application from Mar Thoma Vidyapeeth Goveli, At Goveli, Post Rayta, Taluka Kalyan, Thane, dated 24-09-2026.
- 2) Letter from Sub-Divisional Engineer, PWD Sub-Division No.1, Kalyan, Letter O.W.No. Sub-Division No.1 /Adm./1275 dated 07/10/2026.

With reference to your above mentioned letter, the Sub-Divisional Engineer, PWD Sub-Division No.1 Kalyan, Thane personally inspected the school building of Mar Thoma Vidyapeeth Goveli, At Goveli, Post Rayta, Taluka Kalyan, Thane on 02/09/2026 and as per the Inspection Report, the school building is safe. In this regard a Safety Certificate has been countersigned and issued which is being sent herewith.

ENCL: Certificate

C.C. for information

To,
Sub-Divisional Engineer, PWD Sub-Division No.1, Kalyan.

sd/-
(Sachin P.Patil)
Executive Engineer
PWD No.1
Thane.



BUILDING SAEFTY CERTIFICATE

This is to certify that, the school building of Mar Thoma Vidyapeeth, Goveli, At Goveli, Post Rayta, Taluka Kalyan, Thane was inspected on 02-09-2026 by this department. Based on the Inspection Report and structural condition observed on the said date, it is hereby certified that the said building is structurally safe, stable and fit for use and It is also observed that the school building is well ventilated, has natural lighting and is suitable for use as a school.

Ground Floor	2 Class Rooms, 1 Admin. Office + Toilet, 1 Principal Office + Toilet, 1 Staff Room, 1 Nursery, 1 Play Area, 1 Science Lab, 1 Electric Duct, 1 Fire Duct, 1 Lift Duct, 1 Male Toilet.
First Floor	9 Class Rooms, 1 Computer Lab, 1 Female Toilet , 1 Electric Duct, 1 Fire Duct, 1 Lift Duct, 1 Female Toilet
Second Floor	8 Class Rooms, 1 Conference Room, 1 Electric Duct, 1 Fire Duct, 1 Lift Duct, 1 Male Toilet
Third Floor	7 Class Rooms, 1 Reading Room, 1 Math's Lab, 1 Library, 1 Wellness Room + Toilet, , 1 Electric Duct, 1 Fire Duct, 1 Lift Duct, 1 Female Toilet,

This certificate is issued for the academic year 02-09-2026 to 31-03-2027 subject to the following terms and conditions.

- 1. No structural alterations/changes shall be made to the school building.
- 2. The area shown as Refuse Area shall be used only as a Refuse Area.
- 3. If any of the certificates submitted along with the proposal is cancelled or not renewed, this certificate will automatically become void.
- 4. For the next academic year 2027-2028, the building completion Certificate (CC) and Building Use Permission(OC) must be submitted, failing which future applications for safety certificate will not be processed

Note: If any of the above terms and conditions are violated, this issued certificate will automatically stand cancelled.

SD/-
Sub-Divisional Engineer
PWD No.1
Thane.

SD/-
Executive Engineer
PWD No.1
Thane.

I hereby certify that, I have translated the attached documents into English to the best of my knowledge.

MRS. SAROJA B. PCOJARY
B.Com, BLS,LL.B.

Office at No. 1, 2nd Floor, Chhatral Building,
Opp: Sessions Court, Chhatral, Near Post Office,
Kalyan (West), District: Thane 421301



ATTESTED BY
ABHIN P. GAIKAR
E.A., LL.B.
ADVOCATE & NOTARY
Mrunal Niwas, Dawadi Road,
Golavali, Tal. Kalyan, Dist. Thane.

17 OCT 2026



कार्यकारी अभियंता यांचे कार्यालय
सा.बां.विभाग क्र.१ ठाणे, ८ वा मजला, ठामपा
पार्किंग प्लाझा बिल्डिंग, ज्यूपिटर हॉस्पिटल
जवळ, ठाणे (प)-४००६०१



महाराष्ट्र शासन

दुरध्वनी क्र. ०२२ २५३६९२९३

Web Site:-www.pwd.maharashtra.gov.in

Email :thane1.ee@mahapwd.gov.in

जा.क्र.वि/सा.बां.वि/ठाणे-१/रेखा शाखा/ ८६१०

दिनांक:- ८/१०/२०२६

प्रति,

मारथोमा विद्यापीठ गोवेली,
मु.गोवेली, पो.रायता, ता.कल्याण,
ठाणे.

विषय:- इमारत सुरक्षित असल्याबाबत दाखला देण्याबाबत.

संदर्भ:- १. मारथोमा विद्यापीठ गोवेली मु. गोवेली पो. रायता ता. कल्याण, ठाणे. यांचा
दि. २४/०९/२०२६ रोजीचा अर्ज.
२. उपविभागीय अभियंता, सा. बां. उपविभाग क्र.१, कल्याण यांचे पत्र जा. क्र.
उविअक-१/प्रशा/१२७५ दिनांक ०७/१०/२०२६.

आपले संदर्भित पत्रान्वये मारथोमा विद्यापीठ गोवेली मु. गोवेली पो. रायता ता. कल्याण, ठाणे. या
शाळेच्या इमारतीची उपविभागीय अभियंता, सा. बां. उपविभाग क्र.१ कल्याण, ठाणे यांनी दिनांक २/०९/२०२६
रोजी प्रत्यक्ष पाहणी केली असून अहवालाच्या अनुषंगाने शालेय इमारत सुरक्षित असल्याबाबतचे प्रमाणपत्र
प्रतिस्वाक्षरी करून सोबत पाठविण्यात येत आहे.

सोबत:- प्रमाणपत्र.

(सचिन प्र. पाटील)
कार्यकारी अभियंता
सा. बां. विभाग क्र.१
ठाणे.

प्रत:- उपविभागीय अभियंता, सा. बां. उपविभाग क्र.१ कल्याण, ठाणे यांना माहितीसाठी रवाना.

इमारत सुरक्षिततेबाबत प्रमाणपत्र

प्रमाणित करण्यात येते की, मारथोमा विद्यापिठ गोवेली मु. गोवेली, पो. रायते, ता. कल्याण, जि. ठाणे या शाळेच्या इमारतीची या विभागामार्फत दि.०२/०९/२०२६ रोजी प्रत्यक्ष पहाणी करण्यात आली असून. सदर इमारतीची पहाणी केली असता, त्या दिवशीच्या स्थिती वरून ती संरचनात्मक सुरक्षित व स्थिर असल्याबाबत प्रमाणित करण्यात येत आहे. तसेच शाळेची इमारत हवेशीर, नैसर्गिक प्रकाशमान असून शाळेच्या वापरासाठी योग्य असल्याचे सकृतदर्शनी दिसून येत आहे.


तळमजला:-	२ वर्ग खोल्या, १ एडमिन ऑफीस+ प्रसाधनगृह, १ प्राचार्य ऑफीस+ प्रसाधनगृह, १ स्टाफ रुम, १ नर्सरी, १ प्ले एरीया, १ सायन्स लॅब, १ इलेक्ट्रीक डक्ट, १ फायर डक्ट १ लिफ्ट डक्ट, १ पुरुष प्रसाधनगृह
पहीला मजला:-	९ वर्ग खोल्या, १ संगणक लॅब, १ महीला प्रसाधनगृह, १ इलेक्ट्रीक डक्ट, १ फायर डक्ट १ लिफ्ट डक्ट १ महिला प्रसाधनगृह
दुसरा मजला:-	८ वर्ग खोल्या, १ कॉन्फरन्स रुम, १ इलेक्ट्रीक डक्ट, १ लिफ्ट डक्ट, १ फायर डक्ट १ पुरुष प्रसाधनगृह
तिसरा मजला:-	७ वर्ग खोल्या, १ रिडींग रुम, १ मॅथ्स लॅब, १ लायब्ररी, १ वेलनेस रुम+प्रसाधनगृह, १ इलेक्ट्रीक डक्ट, १ फायर डक्ट, १ लिफ्ट डक्ट, १ महिला प्रसाधनगृह

सदरहु प्रमाणपत्र दि. ०२/०९/२०२६ ते ३१/०३/२०२७ या शैक्षणिक वर्षाच्या कालावधी पर्यंत खालील अटी व शर्तीच्या अधिन राहून सदरील प्रमाणपत्र निर्गमित करण्यात येत आहे.

- १) शाळेच्या इमारतीच्या बांधकामामध्ये कोणतेही संरचनात्मक बदल करण्यात येऊ नयेत.
- २) रिफ्युज एरिया म्हणून दर्शविण्यात आलेला भाग हा केवळ रिफ्युज एरिया म्हणूनच वापर करण्यात यावा.
- ३) प्रस्तावासोबत सादर केलेल्या प्रमाणपत्रांपैकी कोणतेही प्रमाणपत्र रद्द झाल्यास अथवा मुदतवाढ न घेतल्यास सदरील प्रमाणपत्र विधीग्राह्य राहणार नाही.
- ४) शैक्षणिक वर्ष सन २०२७-२८ करिता बांधकाम पूर्णत्वाचा दाखला व इमारत वापर परवाना सादर न केल्यास पुढील इमारत सुरक्षितते बाबत प्रमाणपत्र करिताच्या अर्जाचा कोणताही विचार न करता सदर अर्ज दप्तरी दाखल करण्यात येईल.

वरील अटी शर्तीचा भंग झाल्यास सदर देण्यात आलेले प्रमाणपत्र आपोआपच रद्दबातल ठरेल याची नोंद घेण्यात यावी.


उपविभागीय अभियंता
सा.बां.उप विभाग क्र.१
कल्याण.


कार्यकारी अभियंता
सा.बां.विभाग क्र.१
ठाणे